

20 June 1995

John Deere Horicon Works

HOOD HINGE POST BREAKS

LX172, LX176, LX178, LX186 and LX188 Lawn Tractors
GT242, GT262 and GT275 Lawn and Garden Tractors

Complaint or Symptom:

- Hood hinge post breaks on impact.
- Cannot repair hinge without replacing hood.
- Hood cost a factor, especially on tractors out of warranty.

Solution:

For low cost repair, order and install Hood Pivot Kit (AM122166).

Additional Information:

Kit consists of two truss head bolts, lock nuts, bushings, friction pads, and installation instructions. Installation involves drilling (2) 1/4-in. diameter holes.

Parts:

Hood Pivot Kit (1) AM122166

